

## **2.23 ICPP-MON-P-020 (MW-20-1)**

### **WELL ID: 1074**

1. Project Name: INTEC Well Maintenance for FY 2003
  2. Well Location: INTEC
  3. Date Maintenance Performed: Started: 5/7/03 Completed: 5/7/03
  4. Video Log Information: Video logging was not performed on this well.
  5. Maintenance Performed: Maintenance at MW-20-1 consisted of removing a stainless-steel sampling bailer that had become lodged in the well. A boom truck was used to lower a long probe into the well. The bailer was dislodged and pulled from the hole.
  6. Observations Recorded: The condition of the surface pad and impingement posts is good. No further problems were noted.
  7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT
- Field Lead: B. Reynolds/W. Jolley
- Crew: S. Tawater, M. Becker, and I. Perkes

WELL ID 1074

WELL NAME ICPP-MON-P-020 (MW-20-1)

PROJECT NAME FY 03 Well Maintenance at INTEC

Reason for modification: Removed a down-hole obstruction

Well Modification Log

START DATE 5/7/03

INSTALLATION TEAM Dynatec

END DATE 5/7/03

Is this a pump replacement?

yes

X

no

If yes was pump returned to original depth?

NA

yes

no

Are measurements from top of casing or land surface?

NA

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Well Description

Casing condition	X	Needs repair
Concrete pad	X	
Guard post	X	
Screen	NA	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Comments:

Removed a stuck bailer from the well.

Video Logs: yes no X date

Well jetted /cleaned: yes no X date

Performed by: Dynatec

Signature and date: Roe Reynolds 9/5/03

Figure 2-23. Well modification log for ICPP-MON-P-020.

2-46

## 2.24 TRA-06A

### WELL ID: 763

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: Test Reactor Area (TRA)
3. Date Maintenance Performed:      Started: 6/24/03              Completed: 7/22/03
4. Video Log Information: Video logging was not performed.
5. Maintenance Performed: Dynatec installed three sections of 21-ft, stainless-steel, 1.25-in., discharge pipe. The new pump is located at 549.6 ft bls. Seventy-three feet of electrical cable was added along with a 3-phase, 30A/600V (NEMA #17-L30) electrical plug. To install the lockable well cap, the landing plate had to be modified to a standard landing plate that holds the 1.25-in. discharge pipe, holds the 1-in. access line, and lands on the 6-in. well casing within the 8-in. surface casing. The surface casing was extended to a 16-in. stick-up, and a new well cap was installed.
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

*Well Modification Log*

WELL ID 763 START DATE 6/24/03 END DATE 7/22/03

WELL NAME TRA-06A INSTALLATION TEAM Dynatec

PROJECT NAME Sitewide Well Maintenance FY 03

Reason for modification: Extended surface casing and lowered pump.

Elevation of brass cap? Not Changed

Is this a pump replacement?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	If yes was pump returned to original depth?	<input type="checkbox"/> yes <input checked="" type="checkbox"/> no	Land Surface
Are measurements from top of casing or land surface? _____				
Use diagram explain modification				
<b>Pump Modification</b>				
Type				
Manufacturer				
Model #				
Pump length				
Top of pump	549.6 ft			
Bottom of pump	553.1 ft			
Inlet depth	552.1 ft			
Horse power				
Flow rate				
Head				
Volts, Amps, Kw				
Phase				
Material				
Motor leads/Plugs	30A/600V			
<b>Protective Casing</b>				
Material				
Diameter				
Height above ground (stick-up)	16 inches			
<b>Well Head</b>				
Well Description	Satisfactory	Needs repair		
Casing condition	X			
Concrete pad	X			
Guard post	X			
Screen	NA			
Lock & cap	X			
<b>Discharge Line (Riser Pipe) Modification</b>				
Material				
Diameter				
Height above ground (stick-up)				
Depth BLS	549.6 ft			
<b>Water Level Access Line Modification</b>				
Material				
Diameter				
Height above ground (stick-up)				
Depth BLS				
<b>Measure Point</b>				
Height above ground (stick-up)	Not Modified			
<b>Well Casing</b>				
Material				
Diameter				
Height above ground (stick-up)				
Depth BLS				

Added three 21 ft sections of 1.25 inch stainless steel discharge line and installed a new landing plate.

Video Logs: yes ☐ no ☒ date \_\_\_\_\_

Signature and date: \_\_\_\_\_

Boe Reynolds 8/5/03

Well jetted /cleaned: yes no X date           

Performed by: Dynatec

Figure 2-24. Well modification log for TRA-06A.

## 2.25 LF2-08

### WELL ID: 196

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed: Started: 5/5/03 Completed: 5/27/03
4. Video Log Information: Video logging was performed on 5/27/03.
5. Maintenance Performed: Maintenance at LF2-08 included removing the 2-hp pump, discharge/access pipe, and electrical assembly; installing a new pump; and replacing the electrical wire with new 8-gauge wire equipped with a 30A/600V (NEMA #17-L30) electrical plug. The well was jetted and cleaned on 5/14/03. Approximately 100 gal of water was generated and disposed of by WGS.  
  
The first pump, installed on 5/14/03, was damaged by sand during pumping, and a second pump was installed on 5/27/03. The well modification log shows the specifications for the second pump.
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes



## **2.26 LF2-09**

### **WELL ID: 197**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed: Started: 11/12/02 Completed: 11/21/02
4. Video Log Information: Video logging was not performed on 11/12/02.
5. Deviation Log Information: Gyro-deviation logging was performed on 11/12/02.
6. Maintenance Performed: Maintenance at LF2-09 included removing the pump, discharge/access pipe, and electrical assembly and replacing the old galvanized access line with stainless-steel pipe. Upon completion of well development activities, the original pump was reinstalled to the original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

## WEI I D 197

WELL NAME LF2-09 START DATE 11/12/02 END DATE 11/21/02  
PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03 INSTALLATION TEAM Dynatec

PROJECT NAME	Pump Removal and Borehole Deviation Logging FY 03	INSTALLATION TEAM


Reason for modification: Pump removed to perform deviation logging.

Galvanized access line replaced with stainless steel.

is this a pump replacement? ☐ yes ☐ no

If was pump returned to original depth? ☐ NA ☐ yes ☐ no

Are measurements from top of casing or land surface? Land Surface



Use diagram explain modification

<i>Pump Modification</i>	Type	<div>Not Modified</div>
	Manufacturer	
	Model #	
	Pump length	
	Top of pump	
	Bottom of pump	
	Inlet depth	
	Horse power	
	Flow rate	
	Head	
	Volts, Amps, Kw	
	Phase	
	Material	
Motor leads/Plugs		

## Well Casing

Material	Not Modified
Diameter	
Height above ground (stick-in)	

<i>Well Description</i>	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

## Discharge Line (Riser Pipe) Modification

Material	<del>Not Measured</del>
Diameter	
Height above ground (stick-up)	
Depth BLS	

### Water Level Access Line Modification

Material	Stainless Steel
Diameter	1 in.
Height above ground (stick-up)	Not Modified
Depth BLS	47+ ft b/s

## Measure Point

Height above ground (stick-up)	Not Modified
-----------------------------------	--------------

## Well Casing

Material	<del>Not modified</del>
Diameter	
Height above ground (stick-up)	
Depth BLS	

**Comments:** There was significant amounts of sediment found at the bottom of the well. The old galvanized access line was replaced with stainless.

Video Logs: yes ☒ no ☐ date 11/12/02

Well jetted /cleaned:	yes	no	X	date

Performed by: Dynatec

Figure 2-26. Well modification log for LF2-09.



## **2.27 LF2-10**

### **WELL ID: 198**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed:      Started: 11/12/02      Completed: 11/19/02
4. Video Log Information: Video logging was performed on 11/13/02.
5. Deviation Log Information: Deviation logging was performed on 11/13/02.
6. Maintenance Performed: Maintenance at LF2-10 included removing the pump, discharge/access pipe, and electrical assembly to log the well. Upon completion of well maintenance activities, the original pump, pipe, and electrical cable were reinstalled to the original depths.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 198

WELL NAME LF2-10

PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03

Reason for modification: Pump removed to perform a deviation log on the borehole.

Well Modification Log

START DATE 11/12/02

INSTALLATION TEAM Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

END DATE 11/19/02

Signature and date: Mike Towler 12/10/02

Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ NA ☐ yes ☐ no

Are measurements from top of casing or land surface? NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
--------------------------------	--

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Comments:

The pump and pipe were replaced to their original depths.

Video Logs: yes ☒ no ☐ date 11/13/02

Well jetted /cleaned: yes ☐ no ☒ date

Performed by: Dynatec

Figure 2-27. Well modification log for LF2-10.

2-54

## **2.28 LF2-11**

### **WELL ID: 199**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed: Started: 11/12/02 Completed: 11/19/02
4. Video Log Information: Video logging was performed on 11/13/02.
5. Deviation Log Information: Deviation logging was performed on 11/13/02.
6. Maintenance Performed: Maintenance at LF2-11 included removing the pump, discharge/access pipe, and electrical assembly to log the well. After logging, all original materials were returned to their original depths.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

*Well Modification Log*

WELL ID 199 START DATE 11/12/02 END DATE 11/19/02

WELL NAME LF2-11 INSTALLATION TEAM Dynatec

PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03

Reason for modification: Pump removed to perform a deviation log on the borehole.

Elevation of brass cap? Not Changed

The pump and pipe were replaced to their original depths.

---

*Comments:*

---

*Video Logs:* yes ☒ no ☐ date 11/13/02

*Well jetted /cleaned:* yes ☐ no ☒ date \_\_\_\_\_

*Performed by:* \_\_\_\_\_ Dynatec

---

Signature and date: Mike Towler 12/10/02

2-56

## **2.29 LF2-12**

### **WELL ID: 724**

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed:      Started: 6/4/03              Completed: 6/4/03
4. Video Log Information: Video logging was not performed on this well.
5. Maintenance Performed: Well maintenance on well LF2-12 consisted of reducing the stick-up of a 1/4-in. vapor-port tube and a 1-in. water-access line that extended 4 ft above the 4.5-in. protective casing. Both were cut off below the elevation of the casing so that a lockable well cap could be installed.
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/L. Lopez

Crew: J. Lambert and D. Waddoups

WELL ID 724

WELL NAME LF2-12

PROJECT NAME EY 03 sitewide well maintenance

Reason for modification: Cut riser, install a well cap, reduce well casing stick-up

Well Modification Log

START DATE 6/4/03 END DATE 6/4/03

INSTALLATION TEAM Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ NA ☐ yes ☐ no

Are measurements from top of casing or land surface? NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	NA	
Lock & cap	X	

Water Level/Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	13 inches
Depth BLS	Not Modified

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Comments:

Trimmed excess vapor port and access line to 13 inches stick-up to allow the well cap to close.

Video Logs: yes ☐ no ☒ date 8/5/03

Well jetted /cleaned: yes ☐ no ☒ date 8/5/03

Performed by: Dynatec

Signature and date: Boe Reynolds 8/5/03

Figure 2-29. Well modification log for LF2-12.

## **2.30 LF3-08**

### **WELL ID: 207**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed:      Started: 11/12/02      Completed: 5/27/03
4. Video Log Information: Video logging was performed on 11/13/02 and 5/22/03.
5. Deviation Log Information: Deviation logging was performed on 11/13/02.
6. Maintenance Performed: Maintenance at LF3-08 included removing the pump, discharge/access pipe, and electrical assembly for logging. The video indicated a blockage at 507 ft bls; however, the blockage is well below the pump depth and does not interfere with sampling. After maintenance, sediment was noted during pumping. Video logs were again collected on 5/22/03, revealing sediment and debris. As a result, the borehole was jetted and cleaned on 5/27/03. The pump was reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 207 **Well Modification Log** START DATE 11/12/02 END DATE 11/20/02  
 WELL NAME LF3-08 PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03 INSTALLATION TEAM Dynatec  
 Reason for modification: Pump removed to perform a deviation log on the borehole. Elevation of brass cap? Not Changed  
 Stick up of well casing? Not Changed

Is this a pump replacement? ☐ yes ☒ no If yes was pump returned to original depth? ☐ NA ☐ yes ☐ no  
 Are measurements from top of casing or land surface? NA

Use diagram explain modification

Type	Manufacturer
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification	
Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification	
Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point	
Height above ground (stick-up)	

Well Casing	
Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Protective Casing	
Material	
Diameter	
Height above ground (stick-up)	

Comments: The pump and pipe were replaced to there original locations. There was a blockage at 507 ft that appeared to be a pipe. Deviations were completed on 11/13/02.

Video Logs: yes ☒ no ☐ date 11/13/02 Signature and date: M. Towler 12/10/02  
 Well jetted /cleaned: yes ☐ no ☒ date 11/13/02  
 Performed by: Dynatec

Figure 2-30. Well modification log for LF3-08 (first maintenance).



WELL ID 207

WELL NAME LF3-08

PROJECT NAME Borhole Deviation Logging

Reason for modification: Pump removed for jetting and cleaning.

Well Modification Log

START DATE 5/19/03

INSTALLATION TEAM Dynatec

END DATE 5/27/03

Elevation of brass casing? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☐ yes ☒ no

Are measurements from top of casing or land surface? NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level/Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
--------------------------------	--

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Comments: Cleaned significant amounts of sand from the borehole through jetting and cleaning.

Video Logs: yes ☐ no ☒ date 5/22/03

Well jetted /cleaned: yes ☐ no ☒ date 5/27/03

Performed by: Dynatec

Signature and date: Boe Reynolds 11/24/03

Figure 2-31. Well modification log for LF3-08 (second maintenance).

## **2.31 LF3-10**

### **WELL ID: 727**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed:      Started: 11/12/02      Completed: 11/20/02
4. Video Log Information: Video logging was performed on 11/13/02.
5. Deviation Log Information: Deviation logging was performed on 11/13/02.
6. Maintenance Performed: Maintenance at LF3-10 included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. All well equipment (i.e., pump, pipe, and wire) was then reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID

727

WELL NAME

LF3-10

PROJECT NAME

Pump Removal and Borehole Deviation Logging FY 03

Reason for modification:

Pump removed to perform a deviation log on the borehole.

Well Modification Log

START DATE

11/12/02

END DATE

11/20/02

INSTALLATION TEAM

Dynatec

Elevation of brass cap?

Not Changed

Stick up of well casing?

Not Changed

Is this a pump replacement?

yes

X

no

If yes was pump returned to original depth?

NA

yes

no

Are measurements from top of casing or land surface?

NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Not Modified

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Not Modified

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Not Modified

Measure Point

Height above ground (stick-up)	
--------------------------------	--

Not Modified

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Not Modified

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Not Modified

Comments:

The pump and pipe were replaced to there original locations. The pump top was set at 580 ft bls. Deviation log was performed on 11/13/02.

Video Logs:

yes X no

date 11/13/02

Signature and date:

Mike Towler 12/10/02

Well jetted /cleaned:

yes no X date

Performed by:

Dynatec

Figure 2-32. Well modification log for LF3-10.

2-63

## 2.32 CFA-MON-A-001

### WELL ID: 1077

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed:      Started: 11/13/02      Completed: 11/25/02
4. Video Log Information: Video logging was performed on 11/20/02.
5. Deviation Log Information: Deviation logging was performed on 11/20/02.
6. Maintenance Performed: Maintenance at this well included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. The pump was damaged as it was being lifted from the well and became lodged in the borehole. As a result, a new pump (refer to the well modification logs) was installed at 514 ft bls, with new 8-gauge wire and a 30A/600V plug (NEMA#17-30).
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

**Well Modification Log**

WELL ID 1077

WELL NAME CFA-MON-A-001 START DATE 11/13/02 END DATE 11/25/02

PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03 INSTALLATION TEAM Dynatec


Reason for modification: Pump removed to perform a deviation log on the borehole. Elevation of brass cap? Not Changed

Pump was damaged during removal and was replaced.

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☐ yes ☒ no

Are measurements from top of casing or land surface?      Top of the MP



Use diagram explain modification

Pump Modification	
Type	Submersible
Manufacturer	Grundfos/Franklin Electric
Model #	10S30-34
Pump length	4.58 ft
Top of pump	514 ft bls
Bottom of pump	518.58 ft bls
Inlet depth	517.58
Horse power	3 hp
Flow rate	Not Measured
Head	Not Measured
Volts, Amps, Kw	230V/9.5A/2.2kW
Phase	3 phase
Material	Stainless steel
Motor leads/Plugs	8 gauge/ 30A600V

## Protective Casing

Material	
Diameter	
Height above ground (stick-in)	

Comments:

There was a tight spot where the original pump was damaged at 240-280 ft bls. The pump top was set at 514 ft bls. Deviation log was performed on 11/20/02.

Video Logs: yes X no      date 11/20/02

Signature and date: \_\_\_\_\_  
Mike Towler 12/10/02

Well jetted /cleaned: yes ☐ no ☐ date \_\_\_\_\_

Performed by: Dynatec

Figure 2-33. Well modification log for CFA-MON-A-001.

## **2.33 CFA-MON-A-002**

### **WELL ID: 1078**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed:      Started: 11/14/02      Completed: 11/20/02
4. Video Log Information: Video logging was performed on 11/20/02.
5. Deviation Log Information: Deviation logging was performed on 11/20/02.
6. Maintenance Performed: Maintenance at this well included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. All well equipment (i.e., pump, pipe, and wire) was then reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 1078

WELL NAME CFA-MON-A-002

PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03

Reason for modification: Pump removed to perform a deviation log on the borehole.

Well Modification Log

START DATE 11/14/02

INSTALLATION TEAM Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

END DATE 11/20/02

Signature and date: Mike Towler 12/10/02

Is this a pump replacement?

☐

yes

☒

no

If yes was pump returned to original depth?

☐

yes

☐

no

Are measurements from top of casing or land surface?

☐

yes

☒

no

NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level/Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
--------------------------------	--

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Comments:

The pump and pipe were replaced to their original depths. Deviation log was performed on 11/20/02.

Video Logs: yes X no

date 11/20/02

Well jetted /cleaned: yes no X

date

Performed by: Dynatec

Figure 2-34. Well modification log for CFA-MON-A-002.

2-67

## **2.34 CFA-MON-A-003**

### **WELL ID: 1089**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: CFA
3. Date Maintenance Performed:      Started: 11/14/02      Completed: 11/21/02
4. Video Log Information: Video logging was performed on 11/20/02.
5. Deviation Log Information: Deviation logging was performed on 11/20/02.
6. Maintenance Performed: Maintenance at this well included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. All well equipment (i.e., pump, pipe, and wire) was then reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes



WELL ID 1089

WELL NAME CFA-MON-A-003

PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03

Reason for modification: Pump removed to perform a deviation log on the borehole.

Well Modification Log

START DATE 11/14/02

INSTALLATION TEAM Dynatec

END DATE 11/21/02

Is this a pump replacement?

☐ yes
☒ no

If yes was pump returned to original depth?

☐ NA
☐ no

Are measurements from top of casing or land surface?

NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Water Level/Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Comments:

The pump and pipe were replaced to their original depths. Deviation log was performed on 11/20/02.

Video Logs: yes X no

date 11/20/02

Signature and date: Mike Towler 12/10/02

Well jetted /cleaned: yes no X

date

Performed by: Dynatec

Figure 2-35. Well modification log for CFA-MON-A-003.

## **2.35 M1SA**

### **WELL ID: 765**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: Radioactive Waste Management Complex (RWMC)
3. Date Maintenance Performed:      Started: 11/14/02      Completed: 11/26/02
4. Video Log Information: Video logging was performed on 11/26/02.
5. Deviation Log Information: Deviation logging was performed on 11/26/02.
6. Maintenance Performed: Maintenance at M1SA included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. All well equipment (i.e., pump, pipe, and wire) was then reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

## Well Modification Log

WELL NAME M1SA START DATE 11/14/02 END DATE 11/26/02

PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03 INSTALLATION TEAM Dynatec

END DATE	11/26/02
----------	----------

START DATE	11/14/02
------------	----------

END DATE	11/26/02
----------	----------

Dynatec

## INSTALLATION TEAM

Reason for modification:	Pump removed to perform a deviation log on the borehole.	Elevation of brass cap?	Not Changed

Elevation of brass can? Not Changed

Not Changed


Is this a pump replacement? ☐ yes ☒ no

If yes was pump returned to original depth? ☐ NA ☒ yes ☐ no

If yes was pump returned to original depth?

NA	yes
	no

Are measurements from top of casing or land surface? NA



<i>Pump Modification</i>	
Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing	
Material	
Diameter	
Height above ground (stick-up)	Not Modified

<i>Well Description</i>	Satisfactory	Needs repair
Casing condition	X	
Concrete pad	X	
Guard post	X	
Screen	X	
Lock & cap	X	

Discharge Line (Riser Pipe) Modification

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	
<del>Not Modified</del>	

Measure Point

Height above ground (stick-up)	Not Modified
-----------------------------------	--------------

Well Casing

Material	Not Modified
Diameter	
Height above ground (stick-up)	
Depth BLS	

*Comments:*

---

The pump and pipe were replaced to their original depths.  
Deviation log was performed on 11/26/02.

Video Logs: yes	X	no	date	Signature and date.
			11/26/02	Mike Towler 12/10/02

Well jetted /cleaned:	yes	no	X	date

Performed by: Dynatec

*Signature and date.*

Figure 2-36. Well modification log for M1SA.

## **2.36 M10S**

### **WELL ID: 770**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: RWMC
3. Date Maintenance Performed:      Started: 10/24/02      Completed: 10/24/02
4. Video Log Information: No video logging was performed during abandonment of this well.
5. Maintenance Performed: Well M10S was abandoned. The borehole and casing were filled with bentonite to seal the well. In order to allow the vapor ports to continue to be used, the well casing was not removed from the borehole. The borehole from the bottom of the well (650 ft bls) to 445 ft bls was filled with coated bentonite pellets. From 445 ft bls to land surface, the well was filled with 3/8-in. bentonite chips. Upon completion of the work, the original wellhead box was replaced and locked. A detailed summary of the abandonment activities is on file with the Hydrologic Data Repository (HDR), for further information contact the HDR.
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: INEEL Force Account personnel.



## **2.37 SOUTH-MON-A-001 (M11S)**

### **WELL ID: 1212**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: RWMC
3. Date Maintenance Performed: Started: 5/12/03 Completed: 5/19/03
4. Video Log Information: Video logging was performed on 5/13/03
5. Deviation Log Information: Deviation logging was performed on 5/13/03.
6. Maintenance Performed: Maintenance at M11S included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video, deviation, and gyro-deviation logging. The video indicated a buildup of bacteria in the well. Seven and a half gal of Aquaclear was used to jet the borehole. Once the pH levels were neutral, all well equipment (i.e., pump, pipe, and wire) was reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID 1212

South-MON-A-001 (M11S)

ICDF Borehole Deviation Logging

Perform Deviation and Gyro-Deviation Logs

Well Modification Log

START DATE 5/12/03

INSTALLATION TEAM

END DATE 5/19/03

Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement?

☐

yes

☒

no

If yes was pump returned to original depth?

☐

yes

☐

no

Are measurements from top of casing or land surface? NA

Use diagram explain modification

Pump Modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
--------------------------------	--

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

Comments:

Approximately 7.5 gallons of Aquaclear was injected to aid in cleaning the borehole.

Video Logs: yes X no

date 5/13/03

Signature and date: Boe Reynolds 5/19/03

Well jetted /cleaned: yes X no

date 5/13/03

Performed by: Dynatec

Figure 2-38. Well modification log for SOUTH-MON-A-001.

## **2.38 SOUTH-MON-A-002 (M12S)**

### **WELL ID: 1213**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: RWMC
3. Date Maintenance Performed:      Started: 11/14/02      Completed: 11/22/02
4. Video Log Information: Video logging was performed on 11/21/02.
5. Deviation Log Information: Gyro-deviation logging was performed on 11/21/02.
6. Maintenance Performed: Maintenance at M12S included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. All well equipment (i.e., pump, pipe, and wire) was then reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes



## Well Modification Log

Pump Modification	
Type	Not Modified
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	Not Modified
Phase	
Material	
Motor leads/Plugs	
Protective Casing	
Material	Not Modified
Diameter	
Height above ground (stick-up)	

*Comments:*

---

The pump and pipe were replaced to their original depths.  
Deviation log was performed on 11/21/02.

Video Logs: yes ☒ no ☐ date 11/21/02

Well jetted /cleaned: yes ☐ no ☒ date \_\_\_\_\_

Performed by: \_\_\_\_\_ Dynatec \_\_\_\_\_

Signature and date: \_\_\_\_\_ Mike Towler 12/10/02

Figure 2-39. Well modification log for SOUTH-MON-A-002.

## **2.39 SOUTH-MON-A-004 (M14S)**

### **WELL ID: 1215**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: RWMC
3. Date Maintenance Performed:      Started: 11/25/02      Completed: 11/26/02
4. Video Log Information: Video logging was performed on 11/25/02.
5. Deviation Log Information: Deviation logging was performed on 11/25/02.
6. Maintenance Performed: Maintenance at M14S included removing the pump, discharge/access pipe, and electrical assembly for logging. The USGS performed video and deviation logs. All well equipment (i.e., pump, pipe, and wire) was then reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

**Well Modification Log**

WELL ID 1215

WELL NAME SOUTH-MON-A-004 (M14S) START DATE 11/25/02 END DATE 11/26/02

PROJECT NAME Pump Removal and Borehole Deviation Logging FY 03 INSTALLATION TEAM Dynatec

Reason for modification: Pump Removed to perform a deviation log on the borehole. Elevation of brass cap? Not Changed

<i>Well Description</i>	<input type="checkbox"/> yes	<input checked="" type="checkbox"/> no	<input type="checkbox"/> NA	If pump was returned to original depth?	<input type="checkbox"/> yes	<input checked="" type="checkbox"/> no	Satisfactory	Needs repair
Casing condition							X	
Concrete pad							X	

Are measurements from top of casing or land surface? NA

Use diagram explain modification

Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	

The pump and pipe were replaced to their original depths.  
Deviation log was performed on 11/25/02.

Comments:

Screen	X
Lock & cap	X

Discharge Line (Riser Pipe) Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Water Level Access Line Modification

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point

Height above ground (stick-up)	
Not Modified	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

*Comments:* The pump and pipe were replaced to their original depths.  
Deviation log was performed on 11/25/02.

---

*Video Logs:* yes ☒ no ☐ date 11/25/02 Signature and date: Mike Towler 12/10/02

---

*Well jetted /cleaned:* yes ☐ no ☒ date \_\_\_\_\_

---

*Performed by:* Dynatec

Figure 2-40. Well modification log for SOUTH-MON-A-004.

## **2.40 RWMC-MON-A-013 (A11A31)**

### **WELL ID: 906**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: RWMC
3. Date Maintenance Performed:      Started: 11/15/02      Completed: 12/03/02
4. Video Log Information: Video logging was performed on 11/25/02.
5. Deviation Log Information: Deviation logging was performed on 11/25/02.
6. Maintenance Performed: Maintenance at A11A31 included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. A new 4-in. Grundfos pump was reinstalled to the original depth using the original discharge pipe. The pump was wired with new 8-gauge wire and a 30A/600V plug (NEMA #L17-30).
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WFLI ID \_\_\_\_\_ 906

WELL NAME RWMC-MON-A-013 (A11A31) START DATE 11/15/02 END DATE 12/03/02

PROJECT NAME Pump Removal and Borehole Deviation Logging FY-03 INSTALLATION TEAM Dynatec

Reason for modification: To perform a deviation log on the borehole. Elevation of brass cap? Not Changed


Elevation of brass can? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☐ no ☒ yes

Are measurements from top of casing or land surface? Top of the MP



Use diagram explain modification

Type	4 inch Grundfos
Manufacturer	Grundfos
Model #	10S 20-27
Pump length	3.5 ft
Top of pump	657 ft bls
Bottom of pump	660.5 ft bls
Inlet depth	658.5 ft bls
Horse power	2 hp
Flow rate	Not measured
Head	Not measured
Volts, Amps, Kw	230v, 6.7 amp, 1.5 kW
Phase	3 phase
Material	Stainless steel
Motor leads/Plugs	30 amp, 600volt

### Protective Casing

Material	Not Modified
Diameter	
Height above ground (stick-in)	

**Comments:**  
The pump and pipe were replaced to their original depths. New 8 gauge electrical cable was installed. Deviation log was performed on 11/25/02.

Video Logs: yes	X	no	date	11/25/02	Signature and date:
					Mike Towler 12/10/02

Well jetted /cleaned:	yes	no	X	date

Performed by: \_\_\_\_\_ Dynatec

Figure 2-41. Well modification log for RWMC-MON-A-013.

## **2.41 RWMC-MON-A-066 (OW-2)**

### **WELL ID: 1132**

1. Project Name: Pump Removal and Deviation Logging for FY 2003
2. Well Location: RWMC
3. Date Maintenance Performed:      Started: 11/15/02      Completed: 11/26/02
4. Video Log Information: Video logging was performed on 11/25/02.
5. Deviation Log Information: Deviation logging was performed on 11/25/02.
6. Maintenance Performed: Maintenance at OW-2 included removing the pump, discharge/access pipe, and electrical assembly. The USGS performed video and deviation logs. A weep hole was installed at 622 ft bls. All well equipment (i.e., pump, pipe, and wire) was then reinstalled to its original depth.
7. Observations Recorded: Surface completion pads and impingement posts were in good condition.
8. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: M. Towler/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WEI ID 1132

WEI | NAME RWMC-MON-A-066 (OW-2)

START DATE

11/15/02

END DATE 11/26/02

11/26/02

PROJECT NAME	Pump Removal and Borehole Deviation Logging FY 03	INSTALLATION TEAM

– **INSTALLATION TEAM**

Dynatec

Reason for modification: Pump removed to perform a deviation log on the borehole.

Elevation of brass can? Not Changed


### Stick Up of well casing? Not Changed

Is this a pump replacement?	<input type="checkbox"/>	yes	<input type="checkbox"/>	no
If yes was pump returned to original depth?	<input checked="" type="checkbox"/>	no	<input type="checkbox"/>	yes
			NA	

yes  
no

Are measurements from top of casing or land surface? NA

NA



Use diagram explain modification

Pump Modification	
Type	
Manufacturer	
Model #	
Pump length	
Top of pump	
Bottom of pump	
Inlet depth	
Horse power	
Flow rate	
Head	
Volts, Amps, Kw	
Phase	
Material	
Motor leads/Plugs	

Protective Casing	
Material	
Diameter	
Height above ground (stick-up)	Not Modified

Casing condition	X
Concrete pad	X
Guard post	X
Screen	X
Lock & cap	X

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	
<del>Not Modified</del>	

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	

Measure Point	Height above ground (stick-up)	Not Modified
---------------	--------------------------------	--------------

Material	
Diameter	
Height above ground (stick-up)	
Depth BLS	
Not Modified	

**Comments:**  
The pump and pipe were replaced to their original locations. New 8 gauge electrical cable was installed. Deviation log was performed on 11/25/02. Drilled a weep hole at 622 ft bls.

Video Logs:	yes	X	no	date	11/25/02
-------------	-----	---	----	------	----------

Mike Towler 12/10/02

Well jetted /cleaned: yes no X date

Performed by: Dynatec

Figure 2-42. Well modification log for RWMCMON-A-066.

## 2.42 USGS-009

### WELL ID: 458

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: South of RWMC on the T-1 road
3. Date Maintenance Performed:      Started: 6/30/03              Completed: 9/11/03
4. Video Log Information: Dynatec personnel and the field crew collected a video log on 7/8/03. Due to a significant amount of debris in the borehole, visibility was limited. The need to jet and clean the borehole was noted. A well brush was also noted in the well.
5. Maintenance Performed: Maintenance at USGS-009 included removing the 5-hp pump, discharge/access pipe, and electrical assembly; jetting and cleaning the borehole; installing a new pump (refer to well modification logs); replacing old galvanized pipe with stainless-steel pipe (refer to well modification logs); and replacing the electrical wire with new 8-gauge wire equipped with a 30A/600V plug (NEMA #17-L30). The well brush was removed from the well on 7/14/03 before cleaning and reinstalling the pump.
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes



WELL ID 458

WELL NAME USGS-009

PROJECT NAME FY 03 Sitewide Wide Well Maintenance

Reason for modification: Replace the pump, pipe, wire, jet and clean the borehole; video and log.

START DATE 6/30/03

END DATE 9/11/03

INSTALLATION TEAM Dynatec

Elevation of brass cap? Not Changed

Stick up of well casing? Not Changed

Is this a pump replacement? ☒ yes ☐ no

If yes was pump returned to original depth? ☒ yes ☐ no

Are measurements from top of casing or land surface? Casing

Use diagram explain modification

Pump Modification

Type	Submersible
Manufacturer	Grundfos
Model #	16S50-38
Pump length	5.1 ft
Top of pump	655 ft bls
Bottom of pump	660.1 ft bls
Inlet depth	659.1 ft bls
Horse power	5 hp
Flow rate	Not Measured
Head	613 ft
Volts, Amps, Kw	460V/9.9A/5kW
Phase	3 phase
Material	Stainless Steel
Motor leads/Plugs	8 gauge, 600V/30A plug

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Discharge Line (Riser Pipe) Modification

Material	Stainless Steel
Diameter	1.5 in.
Height above ground (stick-up)	3 ft
Depth BLS	655 ft bls

Water Level Access Line Modification

Material	Stainless Steel
Diameter	1 in.
Height above ground (stick-up)	3 ft.
Depth BLS	625 ft

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Comments:

The video of this well showed excessive amounts of debris so the well was jetted and cleaned.

A well brush found during the video log was also removed.

Video Logs: yes ☒ no ☐ date 7/8/03

Signature and date: Boe Reynolds 8/5/03

Well jetted /cleaned: yes ☒ no ☐ date 7/14/03

Performed by: Dynatec

Figure 2-43. Well modification log for USGS-009.

## 2.43 USGS-019

### WELL ID: 468

1. Project Name: Site-wide Well Maintenance for FY 2003
2. Well Location: Northwest of the Naval Reactors Facility (NRF)
3. Date Maintenance Performed:      Started: 6/11/03              Completed: 7/20/03
4. Video Log Information: The USGS video logged well USGS-019 on 6/17/03. The video showed a slotted carbon-steel screen with rust composite caked on the inside of the screen. The top of a 3/4-in. poly vinyl chloride pipe was visible at 327 ft bls; several pieces of pump tape were also noted.
5. Maintenance Performed: Maintenance at USGS-019 included removing the pump, pipe, and electrical assembly; jetting and cleaning the borehole; removing sediment in the well with a sand pump, installing a new pump (3-hp, 3-phase); replacing old galvanized pipe with stainless-steel pipe (1.25-in. discharge and a 1-in. water access line); and replacing the electrical wire with new 10-gauge wire equipped with a 30A/600V plug (NEMA #17-L30).
6. Observations Recorded: Surface completion pads and impingement posts were in good condition.
7. Maintenance Subcontractor: Dynatec Drilling, Salt Lake City, UT

Field Lead: B. Reynolds/L. Lopez

Crew: G. Jensen, J. Lambert, D. Waddoups, L. Rosario, T. Brower, and I. Perkes

WELL ID

468

WELL NAME

USGS-019

PROJECT NAME

FY 03 Sitewide Wide Well Maintenance

Reason for modification:

Clean, jet, and video; replace galvanized pipe with stainless; and install a working pump.

START DATE

6/11/03

END DATE

7/20/03

INSTALLATION TEAM

Dynatec

Elevation of brass cap?

Not Changed

Stick up of well casing?

Not Changed

Is this a pump replacement?

☒ yes
 ☐ no

If yes was pump returned to original depth?

☐ yes
 ☒ no

Are measurements from top of casing or land surface?

Land Surface

Use diagram explain modification

Pump Modification

Type	4 in. Submersible
Manufacturer	Grundfos/Franklin Electric
Model #	10S30-34
Pump length	4.58 ft
Top of pump	323.7 ft
Bottom of pump	328.28 ft
Inlet depth	327.28 ft.
Horse power	3 horse
Flow rate	Not Measured
Head	279 ft
Volts, Amps, Kw	230V/9.5A/2.2KW
Phase	3 phase
Material	Stainless Steel
Motor leads/Plugs	10 gauge/ 600V/30A plug

Protective Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified

Discharge Line (Riser Pipe) Modification

Material	Stainless Steel
Diameter	1.5 in.
Height above ground (stick-up)	2.5 ft
Depth BLS	323.7 ft

Water Level Access Line Modification

Material	Stainless Steel
Diameter	1 in.
Height above ground (stick-up)	2.5 ft
Depth BLS	Aproximately 304 ft

Measure Point

Height above ground (stick-up)	Not Modified
--------------------------------	--------------

Well Casing

Material	
Diameter	
Height above ground (stick-up)	Not Modified
Depth BLS	

Comments:

There is a 3/4 in PVC pipe located in the well at approximately 327 ft bls. It appeared to have been broken off and lost in the well.

Video Logs:

yes ☐ no ☒ date 6/17/03

Well jetted /cleaned:

yes ☐ no ☒ date 7/20/03

Performed by:

Dynatec

Signature and date:

Boe Reynolds 8/5/03

Figure 2-44. Well modification log for USGS-019.